

Title:	Flagpole in the Library car park leaning.
Description	One of the flagpoles in the Library car park is leaning
Owner:	BPC
Area:	Amenity
Status	BVS/BPC investigating
Last Updated:	14/01/2024

Actions

Date	Action by	Action/Event
14/01/2024	BVS	Investigate best way to correct lean.

Details

One of the flag poles in the library car park is leaning. Last year the BVS replaced the halyards on both flagpoles. The flagpole was leaning then. On checking the base, it appears that the concrete base has shifted. It may be possible to correct the lean by 'shimming' the base plate hinge.

